



Where Automation Connects.



PLX51-DF1-ENI

DF1 to EtherNet/IP
Gateway

January 6, 2026

RELEASE NOTES

Your Feedback Please

We always want you to feel that you made the right decision to use our products. If you have suggestions, comments, compliments or complaints about our products, documentation, or support, please write or call us.

ProSoft Technology, Inc.

+1 (661) 716-5100

+1 (661) 716-5101 (Fax)

www.prosoft-technology.com

ps.support@belden.com

PLX51-DF1-ENI Release Notes
For Public Use.

January 6, 2026

ProSoft Technology®, is a registered copyright of ProSoft Technology, Inc. All other brand or product names are or may be trademarks of, and are used to identify products and services of, their respective owners.

Content Disclaimer

This documentation is not intended as a substitute for and is not to be used for determining suitability or reliability of these products for specific user applications. It is the duty of any such user or integrator to perform the appropriate and complete risk analysis, evaluation and testing of the products with respect to the relevant specific application or use thereof. Neither ProSoft Technology nor any of its affiliates or subsidiaries shall be responsible or liable for misuse of the information contained herein. Information in this document including illustrations, specifications and dimensions may contain technical inaccuracies or typographical errors. ProSoft Technology makes no warranty or representation as to its accuracy and assumes no liability for and reserves the right to correct such inaccuracies or errors at any time without notice. If you have any suggestions for improvements or amendments or have found errors in this publication, please notify us.

No part of this document may be reproduced in any form or by any means, electronic or mechanical, including photocopying, without express written permission of ProSoft Technology. All pertinent state, regional, and local safety regulations must be observed when installing and using this product. For reasons of safety and to help ensure compliance with documented system data, only the manufacturer should perform repairs to components. When devices are used for applications with technical safety requirements, the relevant instructions must be followed. Failure to use ProSoft Technology software or approved software with our hardware products may result in injury, harm, or improper operating results. Failure to observe this information can result in injury or equipment damage.

© 2026 ProSoft Technology. All Rights Reserved.

Printed documentation is available for purchase. Contact ProSoft Technology for pricing and availability.

Contents

Your Feedback Please	2
Content Disclaimer	2
1 Start Here	4
1.1 About the PLX51-DF1-ENI.....	4
1.2 Release Enhancements	5
2 Support, Service & Warranty	8
2.1 Contacting Technical Support.....	8
2.2 Warranty Information.....	8

1 Start Here

This document highlights the new features, fixes, enhancements and known issues for the PLX51-DF1-ENI Gateway module.

1.1 About the PLX51-DF1-ENI

Model	Standards
PLX51-DF1-ENI	UL/cUL; Class1Div2

Wondering what you'll do now that Rockwell Automation has discontinued its legacy 1761-NET-ENI module? ProSoft Technology's DF1 Routing Module can be used in a similar way.

The PLX51-DF1-ENI module provides EtherNet/IP connectivity for SLC™ 500, CompactLogix™ and MicroLogix™ controllers, as well as many other DF1™- enabled devices.

The module can be used for messaging between two controllers, uploading and downloading PLC programs, modernizing HMIs, or migrating legacy Honeywell systems.

1.2 Release Enhancements

Release Version	Release Date	Description
1.003.014	2-Aug-2023	<ul style="list-style-type: none">Added ability to mask the Class 1 UDP indication and added 0x00 as the delimiter in the <i>Name of Service</i> in the ENIP List Services response
1.003.011	20-Jul-2022	<ul style="list-style-type: none">Customers with module version number prior to 1.003.010 will be able to successfully upgrade the module firmware to version 1.003.011 or newer.Customers with module version number 1.003.011 or newer will not be able to downgrade their firmware to 1.003.010 or older.
1.003.010	25-Feb-2022	<ul style="list-style-type: none">Fixed issue where module was sending ACK to other DF1 Slave responses while in Bridge mode.Fixed issue where module did not respond to PCCC message after a DF1 slave communication fault (No response, NAK, EOT, Incorrect TNS).
1.003.009	2-Feb-2021	<ul style="list-style-type: none">Fixed anomaly where a NAK received message was incorrectly handled when the module is operating as a HD Slave.Fixed anomaly where an online edit and/or a download to a PLC5 / SLC via the DF1 Router would fail.
1.003.008	13-Nov-2020	<ul style="list-style-type: none">Added DF1 Slave ENQ unloading when wrong TNS was received.Fixed issue where each packet coming from <i>DF1_receive_pccc</i> must use a different DST node to avoid confusion on the response.Fixed issue where there was no response to PCCC TCP SYN requests when PCCC enable was not set.Fixed issue - In HD mode, the response packets from other devices are seen as checksum errorsFixed Issue - Unloading HD response once the ACK has been received. If no ACK, then resend the same responseFixed issue - When DF1 is in Slave mode, mapping would use the length of mapped item. For example, N100 to be mapped to N10, because it only looks at the N10 characters. In <i>DF1_get_tag_map</i> function length should match.
1.003.006	7-Jan-2020	<ul style="list-style-type: none">Fix anomaly where module incorrectly detects the end of the packet when multiple 0x10 (DLE) are sent before the 0x03 (ETX) byte.
1.003.005	12-Dec-2019	<ul style="list-style-type: none">Fixed Scheduled SLC Read/Write for file numbers over 99.Fixed issue where in Bridge Mode HD Master - cannot send from node 16Added processing and capture of EOT packet

1.003.004	15-Oct-2019	<ul style="list-style-type: none">When replying in bridge mode - HD Slave - if ACK was not received in time, it will not send ENQThe source address in bridge mode - HD Master - configurable using Node Address parameter in the Serial - DF1 configuration tab of PLX50CU. <p>Known Issues:</p> <ul style="list-style-type: none">When the PLX1-DF1-ENI is operating as a DF1 half-Duplex Master, there is a slight probability that a single message will be ignored. Any following message will work as designed.
1.003.003	2-Sep-2019	<ul style="list-style-type: none">In Half duplex communication mode, ACK will not be sent if destination address is NOT in mapFixed – DF1 communications may become unresponsive if the link to the Logix controller was broken, while the Ethernet Link on the module is still up, and DF1 messages are received frequently without any timeout on the DF1 Master
1.003.002	21-Jun-2019	<ul style="list-style-type: none">Added Micro RevisionUpdated ARP behaviour to not fill up with broadcast messagesFixed issue where PCCC message buffer rejects messages when there are more than 3 buffered (should be 5).Added support for DF1 Half Duplex Master when in bridge mode.Support for SLC FNC 0xAB in Slave mode which is Masked writeSupport for PLC5 Typed Write with only a single element (non - array) in slave modeAdded DIP4 forcing the module to fixed IP address 192.168.1.100Updated ENIP connection to use Default Gateway Address when destination IP address is out of subnet.Fixed webserver micro revision
1.003	17-Aug-2018	<ul style="list-style-type: none">Half-duplex checksum anomaly was resolved when in Scheduled mode.Fixed anomaly with the DF1 Router where excessively large packets (during a download PLC download) could cause the module to reset.Fixed anomaly with the DF1 Router where, if certain malformed PCCC packets are received, could cause the DF1 Router to reset.Enhancement to limit the amount of consecutive ENQ requests (this came from a customer who was interfacing the DF1 Router with an old DeltaV driver) allowing older drivers to recover once disconnected.Enhancement to address anomaly in SLC5/04 and SLC5/03 which could cause the SLC controller to suffer an unrecoverable fault when programming while a PanelView is connected to the SLC via the DF1 Router (this came from Melbourne Water in Australia).

		<ul style="list-style-type: none">Minor enhancements to the Ethernet stack to comply with Achilles Level 1+2.
1.002	23-Jan-2018	<ul style="list-style-type: none">Fixed issue where certain routed PCCC messages did not send to the correct destination address.Fixed minor anomalies in the CIP statisticsResolved issue where forward open from CIP Serial connection could cause the Class 1 EtherNet/IP connection to drop.
1.001	20-Dec-2017	Initial Release

2 Support, Service & Warranty

2.1 Contacting Technical Support

ProSoft Technology, Inc. is committed to providing the most efficient and effective support possible. Before calling, please gather the following information to assist in expediting this process:

- 1 Product Version Number
- 2 System architecture
- 3 Network details

If the issue is hardware related, we will also need information regarding:

- 1 Module configuration and associated ladder files, if any
- 2 Module operation and any unusual behavior
- 3 Configuration/Debug status information
- 4 LED patterns
- 5 Details about the interfaced serial, Ethernet or Fieldbus devices

North America (Corporate Location)	Europe / Middle East / Africa Regional Office
Phone: +1 661-716-5100 ps.prosofttechnology@belden.com Languages spoken: English, Spanish	Phone: +33.(0)5.34.36.87.20 ps.europe@belden.com Languages spoken: English, French, Hindi, Italian
REGIONAL TECH SUPPORT ps.support@belden.com	REGIONAL TECH SUPPORT ps.support.emea@belden.com
Latin America Regional Office	Asia Pacific Regional Office
Phone: +52.222.264.1814 ps.latinam@belden.com Languages spoken: English, Spanish, Portuguese	Phone: +60.3.2247.1898 ps.asiapc@belden.com Languages spoken: Bahasa, Chinese, English, Hindi, Japanese, Korean, Malay
REGIONAL TECH SUPPORT ps.support.la@belden.com	REGIONAL TECH SUPPORT ps.support.ap@belden.com

For additional ProSoft Technology contacts in your area, please see:
www.prosoft-technology.com/About-Us/Contact-Us

2.2 Warranty Information

For details regarding ProSoft Technology's legal terms and conditions, please see:
www.prosoft-technology.com/ProSoft-Technology-Legal-Terms-and-Conditions

For Return Material Authorization information, please see:
www.prosoft-technology.com/Services-Support/Return-Material-Instructions