Letter issued under the responsibility of



Nemko USA, Inc.

2210 Faraday Ave, Suite 150, Carslbad, CA, 92008

Phone (769) 444-3500, Fax (760) 444-3005

LETTER OF CONFORMITY

Ref. No. 402275-ATX-1, 402275-ATX-2

Issue Date:

Product

Name and address of the manufacturer

Trade mark (if any).

Model/Type Ref.

Required marking:

Summary of the test results:

A sample of the product has been tested and found to be in conformity with the current standard, (number and edition):

Special Conditions for Use:

August 06, 2020

Communication module intended for use in industrial control applications. Devices are DC powered and use a variety of communications protocols. See individual reports for further descriptions.

Aparian Inc.

24 Twain, Irvine, CA, 92617, United States

aparian or Prosoft

Aparian: A-DF1R, A-MBR-485, A-TSM, A-J1939R, A-DNP3-M/B, A-DNP3-S/B, A-DH485R/B, A-HRT-4I and A-HRT-4O

ProSoft: PLX51-DF1-ENI, PLX51-DF1-MSG, PLX51-DL-232, PLX51-DLplus-232, PLX51-XGPS, PLX51-MB-232, PLX51-RMG, PLX51-DHCP, PLX51-DNP3, PLX51-GML, PLX51, PLX51-MB-485, PLX51-DH485, PLX51-BACNET, PLX51-TS, PLX51-DNTR, PLX51-J1939, PLX51-CANOPEN, PLX51-DNPM, PLX51-DNPS, PLX51-AB-SER, PLX51-HART-4I and PLX51-HART-4O

(Ex)

II 3 G Ex nA IIC T5 Gc -20 °C ≤ Ta ≤ 70 °C

IEC 60079-0:2011, 6th Edition and IEC 60079-15:2017, 5th Edition

Based on the findings of the assessment of the equipment to the requirements of IEC 60079-0:2011 and IEC 60079-15:2017, reports provided to manufacturer, and the results of the type testing, the product was found to meet all of the applicable requirements of the standards as described in the assessment. Refer to Nemko test reports Ref. No. 402275-ATX-1, and 402275-ATX-2.

N/A

This "Letter of compliance" is the result of testing a sample of the product submitted, in accordance with the provisions of the relevant specific standard.

This "Letter of compliance" is not a certificate and may not be used as one.

Note that although IECEX reports were provided as supporting documents to this report, the reports were not issued by an IECEX Testing Laboratory or Certification Body, and IECEX certification is not implied.

Issued By:

Hauke Reinhardt Sr. Safety Engineer

Il WillMA